# **CCR CELL NOS. 3 & 8 ANNUAL INSPECTION**

### BY

## QUALIFIED PROFESSIONAL ENGINEER AS REGUIRED UNDER OAC 252:517-13-5(b)(1)

Facility Name:	Big Fork Ranch			
Solid Waste Permit Number:	3552014			
Permittee:	Evans & Associates Construction Co.,		ion Co., Inc.	
Inspection Period:				
Date of Field Inspection:	9-12-22			
Review Previous Weekly and Annual Inspections	Yes	Х	No	

Foundation: (stability, lack of vegetation, removal of topsoil)

	Yes	No	N/A
Foundation appears stable	X		
Any seepage in the area of the foundation or pile		Х	
Potential structural weakness		Х	

### Foundation Comments / Corrective Actions:

NONE					

**Construction and Stability:** (description of material, compaction, lift thickness, slopes, construction methods)

	Yes	No	N/A
Lifts are adequately compacted	Х		
Tension cracks noted along surface of pile		Х	
Base of pile appears stable	X		
Side slopes of pile appear stable	Х		
Any indication of potential failure or instability, slumping or structural weakness		Х	

## Construction and Stability Comments / Corrective Actions:

NONE	

Drainage: All drainage structures appear to be working properly.

	Yes	No	N/A
Drainage around pile is in place and appears adequate	X		
Signs of erosion along ash product pile		Х	
Surface of pile is sloped to prevent water ponding	X		

Drainage Comments / Corrective Actions:  NONE	
Volume of CCR in the Cells: 62,689.69 (cu. yd.	) on <u>9-13-22</u> (date)
Changes in CCR Fill Stability and Geometry Since NONE	Last Annual Inspection:
General Comments: NONE	
Inspected By:  Saeed Zahrai. P. E.  Printed Name  9-13-22  Date  P. O. Box 2228, Edmond, Ok 73083  Address  405-557-0000  Telephone	M. SAEED ZAHRAI 18138  OKLAHOMERINA  OKLAHOM
Professional Engineer Registration No. <u>18138</u>	_ (Seal)